

**KAISER****MARQUARDT****RED FLAG TWX (FINAL REPORT)**

PAGE 1 OF 86

**FAILURE MALFUNCTION REPORT**

DATE OF FAILURE/MALFUNCTION

REPORT NO.

**SYMPTOMATIC REPORT**

05/23/97

5285-001 REV. A

ITEM	NAME	PART OR MODEL NUMBER	MANUFACTURER	SERIAL NUMBER	OPERATING TIME/CYCLE
FAILED ITEM	INJECTOR ASSY.	X42881	KAISER MARQUARDT	N/A	UNKNOWN
NEXT ASSY					UNKNOWN
END ITEM	CALORIMETER CHAMBER ASSY.	X42880	KAISER MARQUARDT	N/A	UNKNOWN

WHAT OPERATION FAILURE DISCOVERED ?

HOT-FIRE TEST

REPLACEMENT PART NO.

NONE

RELATED IRR, FMR, ETC.

N/A

REPLACEMENT SERIAL NO.

N/A

WHAT WERE INDICATIONS &amp; SUSPECTED CAUSE OF TROUBLE ?

During Run No. 1038 a 1 second test, the test article was damaged by fire. Post test inspection revealed that the Hydrogen inlet fitting to the injector was consumed, and the hydrogen line was separated from the test article.

ITEM

ELAPSED TIME (MAN HOURS)

TROUBLESHOOTING

Hrs

REPAIR

Hrs

FUNCTIONAL TEST

Hrs

INSPECTION

Hrs

DOCUMENTATION

Hrs

REPORTED BY

Bob Humphrey

DATE 7-14-97

CONT'D ON PAGE

DEPT. NO.

7870

SUPERVISOR

**FAILURE ANALYSIS REPORT**

WHAT WAS THE CAUSE OF THE FAILURE ?

The cause of the hot fire failure was LOX and GH<sub>2</sub> mixing and burning internally at the Hydrogen feedline prior to injector interface. The root cause for the fire has been traced to the GN<sub>2</sub> purge check valve on the LOX feed system. The internal components of the check valve were installed incorrectly allowing Oxygen flow into the Hydrogen feed system then into the injector.

CONT'D ON PAGE

2

RELATED IRR, FMR, EO, ETC.

ANALYZED BY

Bob Humphrey

Jeff Mays

DATE

7-14-97

DEPT. NO.

7870

**EVALUATION**

EVALUATION &amp; CORRECTIVE ACTION

SEE PAGE 4 FOR EVALUATION &amp; CORRECTIVE ACTION.

CONTINUED ON PAGE

4

RELATED CORRECTIVE ACTION DOCUMENTS (EOs, ETC.)

RELEASE DATES

PROGRAM MANAGER CONCURRENCE

DATE

RELIABILITY CONCURRENCE

EFFECTIVITY

CORRECTIVE ACTION RESPONSIBILITY

## WHAT WAS THE CAUSE OF FAILURE? (continued from cover page):

### THE INVESTIGATION

The hot fire test was conducted for a 1 second duration with inlet pressures set at 1210 psia Hydrogen, and 1071 psia LOX. Shut down occurred at the end of the one second pulse. Post test inspection revealed that the Hydrogen inlet fitting to the injector was consumed, and the Hydrogen line was separated from the test article. The Calorimeter injector; GH<sub>2</sub> flex line; and connection fitting were removed from the test cell and brought up to Engineering for evaluation. The initial post test observations of the hardware and cell connections indicated a violent, high temperature combustion event had occurred. These observations were based on the fact that the hydrogen inlet tube, flex hose fitting, and connector fitting were melted and damaged. There was metallic slag on the injector face, as well as in the chamber. Black deposits were also observed on the injector face. The interior portion of the injector was melted. The Teflon coating in the Hydrogen flex line was in very good condition. There was a build-up of slag in the Calorimeter chamber. Flake particles were dispersed around the test item, on the supporting bracket and on the test cell floor. The test cell was sealed off until photographs and collection of failure evidence was performed.

Figures 1 through 15 photo document the conditions of the hardware as described above, immediately after the failure. Figures 1 through 4 show the injector face and injector inlets. On the face of the injector, a black 'sooty' deposit was observed. In Figure 3, the GH<sub>2</sub> inlet damage is shown. Figures 5 through 8 show the interior condition of the injector as first viewed through the inlets using a borescope. Figure 9 shows the fitting connecting the GH<sub>2</sub> flex line to the injector. Figures 10 & 11 show the interior condition of the flex line. The white material observed in these figures is Teflon. The next set of photographs were taken in the test cell. Figures 12 & 13 are the Calorimeter Chamber, downstream from the injector. Note the 'slag' build-up in the chamber. Figure 14 shows a 'flake' particle which came to rest behind the injector/chamber assembly. Figure 15 shows a collection of 'flake' particles observed below the injector/chamber assembly on the test cell floor.

A Failure Investigation Committee (F.I.C.) was formed to follow-up on the investigation. The F.I.C. was chaired by Reliability, and members were brought in from Project, Manufacturing, Materials, and Data Engineering. A "Fish-Bone" diagram was assembled with input from all members of the F.I.C., SEE Figure 16. The different legs of the fish-bone were evaluated by both the responsible member of the F.I.C. and the chairman.

The first leg reviewed was the Procedures. In this section there were three sub-categories. They were the "set-up" list, the "check-off" list, and the test procedure. All three items were covered in a Test Readiness Review (TRR), performed on May 19, 1997 SEE ATTACHMENT I. At that time, a system schematic of the piping and instrumentation was included, See Figure 17. The initial system schematic differs from the actual set-up which was physically verified after the failure, See Figure 18.

The difference between the two schematics are as follows. The initial system schematic introduced during the TRR, indicated separate GN2 supply systems to the propellant lines. In the actual set-up schematic, the GN2 purge lines are common to both sides of the propellant system. The second difference is where the GN2 purge line enters the Hydrogen system. On the initial schematic, the purge is shown upstream of the Hydrogen check valve. In actuality, the purge enters the system downstream of the Hydrogen check valve. The "check-off" list and the actual Hot Fire Test procedure encompassed all necessary items to perform a successful test.

The Material compatibility was examined, as was the cryogenic properties. The Oxygen Free copper #C10200 employed in the design conforms to this application for both compatibility and cryogenically usage. The stainless steel plenum seal plates, and inlet fittings were also found to conform to this application, based on a literature search. The Material leg was eliminated as a contributing factor of the failure.

On the Manufacturing leg, all the operations listed were verified to have been performed per requirements. However, during proof pressure test, the injector was pressurized internally to 1,000 psid. The internal pressure was not the concern. The concern here was for the pressure which was downstream of the injector into the test fixture cavity. The pressure in the cavity caused the injector to flex and bend outward by 0.015in. The injector was straightened to within 0.001in. The injector was pressurized to 1,000 psid with a different configuration downstream.

However, the injector still flexed and bent 0.007in. Again the injector was straightened to within 0.001in. No damage was noted as a result of the distortions. No other anomalies were observed or discovered in the manufacturing or processing of the hardware.

On the Design leg, the 'TEST SYSTEM' has been already addressed in this report. The wall thickness between the plenums and passages was reviewed with KM's stress expert. ATTACHMENT II of this report is the MEMO issued with the results. The conclusion of the report is that excessive stress was not a contributing factor in the failure of the injector.

The injector was sectioned parallel to the injector face through the  $\text{GH}_2$  plenum. Figures 19, 20, and 21 show the sectioned halves of the injector. With these photographs, it is plain to see where the internal burning occurred. The plenum wall between the LOX and  $\text{GH}_2$  has been burnt away. The sectioned halves were subjected to Scanning Electron Microscopy analysis. The first item examined was the injector half with the injector face. The black 'sooty' deposit observed on the face was analyzed and found to be copper/Stainless Steel mixture with some Carbon, and Teflon, See Figures 22 & 23. The Carbon residue is most likely the result of using "shop-air" in the ignitor. Any oil in the "shop-air" would have been combusted leaving behind the black, 'sooty' deposit. The Teflon found on the injector face appears to have come from the Teflon material lining the Hydrogen inlet flex line. The 'slag' observed on the injector face was found to be copper/stainless steel mixture. A high amount of Oxygen was observed in both traces. No Teflon was observed, See Figures 24 & 25.

The interior edges were inspected at 12x and 18x magnification. The edges indicate molten melting of the material, rather than destruction from an explosion, See Figures 26 & 27. The Thermocouple removed from the LOX side of the system was analyzed. No copper slag was present, See Figure 28. This is significant in showing that there was no "blowback" up the LOX side of the system. Hence forward flow was constant throughout the test. The 'flake' particle observed on the bracket behind the injector matches elementally to the injector, See Figure 29. Looking at the 10x mag. photograph in Figure 30, the pattern of the four internal holes is still visible.

The data from the 'cold-flow' tests was compared to the hot-fire flow data. Several anomalies were observed. First anomaly observed is the slow rise in Chamber pressure during the hot-fire. The chamber pressure rose at a significantly faster rate during the cold-flow test. The second anomaly noted is a change in the flow of the Hydrogen at about 1 second into the test. It is after this point that there was internal burning in the injector taking place, See Figure 31. This anomaly was not observed in the GH2 cold-flow test run #1005, See Figure 32. No anomalies were observed in the LOX cold flow test, run #1004, Figure 33.

The final anomaly observed was a recorded temperature of +200°F at T<sub>c</sub> 'LTT' after ignition spike on the LOX side of the system, (approximately 4" from the injector head), See Figure 34. No other temperature anomalies were observed. Detail test data analysis indicated that the failure could have occurred at the GN2 check valve on the LOX system, resulting in LOX flow into the Hydrogen system. (SEE ATTACHMENT III ANALYSIS REPORT by RON COOK).

The GN2 check valve was removed from the test set-up and flow tested with GN2. The check valve flowed in both directions with inlet pressures of 2 to 2,000 psia. The internal components were removed, and examined. Physical verification of the GN2 purge check valve was performed. The internal components were verified to be installed incorrectly allowing for flow through the check valve in both directions See Figure 35.

## **EVALUATION & CORRECTIVE ACTION (continued from cover page.):**

### **EVALUATION:**

As a result of the incorrect assembly of the  $\text{GN}_2$  check valve used in the purge system, both sides of the propellant feed systems were subjected to LOX during the flow tests. The LOX flowed through the common purge line and into the Hydrogen side. The detonation in the chamber forced high temperature combustion gasses into the LOX and  $\text{GH}_2$  feed systems, which started the burning process at the  $\text{GH}_2$  line to injector interface.

### **CORRECTIVE ACTION:**

Remove the remaining check valves in the system, and verify proper installation of internal components and functionality.

The following is a list of recommendations which should be employed in the program as it progresses forward.

### **HARDWARE:**

- During build-up of the replacement injector, if a processing anomaly occurs, bring together the entire RBCC team to discuss and evaluate.
- At critical processing points, employ test coupons...i.e. brazing, etc.

### **TEST SET-UP:**

- Use separate purge sources, if possible, or use double check valves in purge lines to prevent backflow.
- Do not 'cold-flow' propellants through the injector prior to the test.
- Do not use 'shop air' for igniter.
- Do not 'pulse' igniter during start-up.
- Verify start-up ignition at lower pressure.
- Modify LOX and  $\text{GH}_2$  plumbing to provide adequate purge and propellant flows.

- Move after-burner flare to within 3" of nozzle exit.
- SEE ATTACHMENT IV MEMO REGARDING CALORIMETER TEST PLUMBING & OPERATIONS MODIFICATIONS

**DATA RECORDING:**

- Employ high speed video (400 to 450 fps) for future tests, use time coding feature.
- Data recorders should be on at all times during test.
- Provide a graphical display of critical test parameters.




FIGURE 1- THE INJECTOR FACE



FIGURE 2- CLOSE-UP OF BLACK "SOOTY" DEPOSIT ON THE INJECTOR FACE.






FIGURE 3- OVERALL VIEW OF THE INJECTOR FROM THE HYDROGEN INLET SIDE.




FIGURE 4- OVERALL VIEW OF THE INJECTOR FROM THE LOX INLET SIDE.



FIGURE 5- VIEW OF THE INTERIOR PORTION OF THE INJECTOR FROM THE LOX INLET.




FIGURE 6- CLOSE-UP VIEW OF THE INJECTOR INTERIOR FROM THE LOX INLET.



FIGURE 7- VIEW OF THE INTERIOR PORTION OF THE INJECTOR FROM THE HYDROGEN INLET.




FIGURE 8- CLOSE-UP VIEW OF THE INJECTOR INTERIOR FROM THE HYDROGEN INLET.

FIGURE 10 - BORESCOPE VIEW OF THE INTERIOR PORTION OF THE FLEX TUBE NEAR THE BURNT OFF SECTION.



FIGURE 9 - OVERALL VIEW OF THE CONNECTOR FITTING BETWEEN THE HYDROGEN FLEX LINE AND THE INJECTOR.






FIGURE 11- BORESCOPE VIEW OF THE INTERIOR PORTION OF THE FLEX TUBE FROM THE END OPPOSITE THE BURNT SECTION.




FIGURE 12- OVERALL VIEW OF THE CALORIMETER CHAMBER.




FIGURE 13-CLOSE-UP OF THE CALORIMETER CHAMBER SHOWING THE SLAG BUILD-UP.

FIGURE 14-"FLAKE"  
PARTICLE WHICH  
CAME TO REST BEHIND  
THE TEST ARTICLE  
ON A BRACKET.





FIGURE 15-"FLAKE" PARTICLES WHICH WERE OBSERVED ON THE FLOOR  
OF THE TEST CELL BELOW THE TEST ARTICLE.




FIGURE-16



# PIPING AND INSTRUMENTATION DIAGRAM




FIGURE 17

# PIPING AND INSTRUMENTATION DIAGRAM




FIGURE 18




FIGURE 19-OVERALL VIEW OF THE INJECTOR INTERIOR AFTER SECTIONING.




FIGURE 20- INTERIOR PORTION OF THE INJECTOR AFTER SECTIONING. THIS IS THE VIEW LOOKING OUT TOWARDS THE INJECTOR FACE.






FIGURE 21- INTERIOR PORTION OF THE INJECTOR AFTER SECTIONING THROUGH THE HYDROGEN PLENUM. IN THIS VIEW WE ARE LOOKING OUT THROUGH THE LOX INLET.



**FIGURE 22 - SEM/EDAX ANALYSIS OF INJECTOR FACE AT 5KV**



**FIGURE 23 - SEM/EDAX ANALYSIS OF INJECTOR FACE AT 20KV**




FIGURE 24 - SEM/EDAX ANALYSIS OF INJECTOR FACE AT 5KV




FIGURE 25 - SEM/EDAX ANALYSIS OF INJECTOR FACE AT 20KV

FIGURE 27- INTERIOR PORTION OF THE INJECTOR SURFACES AFTER SECTIONING. NOTE THE "MOLTEN FLOW" SURFACE CONTOURS.







FIGURE 26- INTERIOR PORTION OF THE INJECTOR SURFACE AFTER SECTIONING. NOTE THE "MOLTEN FLOW" SURFACE CONTOURS.





**FIGURE 28 - SEM/EDAX ANALYSIS OF INJECTOR FACE AT 5KV**



**FIGURE 29 - SEM/EDAX ANALYSIS OF INJECTOR FACE AT 20KV**








FIGURE 30- OVERALL VIEW OF THE "FLAKE" PARTICLE FOUND ON THE BACK MOUNTING BRACKET BEHIND THE ENGINE. THE YELLOW ARROWS HIGHLIGHT THE 4 HOLES.


## HOTFIRE RESPONSE - R1038



GH2 RESPONSE - RUN 1005



LOX SYSTEM RESPONSE



# RUN 1038 - LOX RESPONSE





FIGURE - 34


FIGURE 35

FLOW



"AS-BUILT"

FLOW



SHOULD BE

**ATTACHMENT I**  
**TEST READINESS REVIEW**

# **RBCC CALORIMETER**

## **TEST READINESS REVIEW**

DATE: 05-19-97



# TEST OBJECTIVES

- Experimentally Determine Heat Transfer Coefficients of the Combustion Chamber to Allow Greater Accuracy of Ejector Coolant Requirements
- Evaluate Ignition Characteristics to Establish Safe, Reliable Startup of Actual Hardware
- Validate Run Procedures - For Future Testing (Regen, Direct/Connect, Freejet)
- Demonstrate Injector Performance and Operation at Various Mixture Ratios (6,7,8,9)
- Verify Overall Performance and Minimum Required Chamber Length
- Demonstrate Reliable H<sub>2</sub>/Air Ignitor System to Achieve Reliable Starts


# TESTING METHODOLOGY

- ✓ Develop Test Plan, Test Matrix, and Facility Operating Requirements
- ✓ Develop Testing Procedures
- ✓ Develop Facility Operating Procedures
- ✓ Identify Critical System Characteristics
- ✓ Design, Layout, and Fabricate Test Setup
- ✓ Perform Hardware Functional Testing
- ✓ Perform System Checkout
- ✓ Experimentally Determine Critical System Characteristics (Waterflow,  $\text{GH}_2$  Cold Flow, LOX Cold Flow)
  - Perform Testing “Dry Runs” for Procedure/System Familiarity
  - Perform Actual Testing

# SEQUENCE OF TESTING


- ✓ WATERFLOW CHECKOUT
  - Validate Coolant System Operation
  - Determine Data Reduction Program Acceptability
- ✓ IGNITOR CHECKOUT
  - Verify Operability and Performance
  - Determine System Lags
- ✓ GH2 COLD FLOW RESPONSE CHECK
  - Validate Controls Operability and Final System Proof
  - Characterize System Response (Perform 3 Times for Repeatability)
- ✓ LOX COLD FLOW RESPONSE CHECK
  - Validate Controls Operability and Final System Proof
  - Characterize System Response & Fluid Quality (3 Times for Repeatability)
- DATA ANALYSIS & REVIEW, APPEND TEST PLAN FOR VALVE LEADTIMES & MODIFY TEST MATRIX AS REQUIRED
- PERFORM HOTFIRE TESTING

# TEST HARDWARE



# SYSTEM SCHEMATIC

## PIPING AND INSTRUMENTATION DIAGRAM



# TEST MATRIX

## COLD FLOW

SYSTEM CHECK OUT	IGNITOR SYSTEM		EJECTOR								COOLING WATER SYSTEM		GN2 PURGE SYSTEM	
	Air	GH2	GH2 SUPPLY			LOX SUPPLY		CHAMBER PRESSURE		MIXTURE RATIO			LOX	GH2
	IAP	IHP	HPS	HTP	GH2 Flowrate	OPT	Flowrate	PT1	PT2		PWCI	FMW	LPI	HPI
	(Psia)	(Psia)	(Psia)	(Psia)	Lbm/sec	(Psia)	Lbm/sec	(Psia)	(Psia)		(Psia)	Lbm/sec	(Psia)	(Psia)
WATER FLOW CHECK	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	TO BE DETER- MINED	>4.432	N/A	N/A
IGNITOR	100	100									1500	>4.432	250	250
SYSTEM	200	200	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	1500	>4.432	250	250
CHECK	300	300									1500	>4.432	250	250
LOX						1071	0.880				1500	>4.432	500	500
COLD	N/A	N/A	N/A	N/A	N/A	1202	0.933	N/A	N/A	N/A	1500	>4.432	500	500
FLOW/ RESP.						1339	0.985				1500	>4.432	500	500
						1471	1.033				1500	>4.432	500	500
GH2			>1600	939	0.115						1500	>4.432	500	500
COLD	N/A	N/A	>1600	1012	0.124	N/A	N/A	N/A	N/A	N/A	1500	>4.432	500	500
FLOW/ RESP.			>1600	1110	0.136						1500	>4.432	500	500
			>1600	1200	0.147						1500	>4.432	500	500

# TEST MATRIX

## HOT FIRE

Run Duration  (seconds)	IGNITOR SYSTEM		EJECTOR								COOLING WATER SYSTEM		GN2 PURGE SYSTE	
	Air GH2		GH2 SUPPLY			LOX SUPPLY		CHAMBER PRESSUR		MIXTURE RATIO				
	IAP	IHP	HPS	HIP	GH2 Flowrate	OPT	Flowrate	PT1	PT2		PWCI	FMW	LPI	HPI
	(Psia)	(Psia)	(Psia)	(Psia)	(lbm/sec)	(Psia)	(lbm/sec)	(Psia)	(Psia)		(Psia)	(lbm/sec)	(Psia)	(Psia)
1	*	*	>1600	1200	0.147	1071	0.880	500	500	6	1500	>4.432	500	500
2	*	*	>1600	1200	0.147	1071	0.880	500	500	6	1500	>4.432	500	500
5	*	*	>1600	1200	0.147	1071	0.880	500	500	6	1500	>4.432	500	500
10	*	*	>1600	1200	0.147	1071	0.880	500	500	6	1500	>4.432	500	500
10	*	*	>1600	1200	0.147	1071	0.880	500	500	6	1500	>4.432	500	500
2	*	*	>1600	1110	0.130	1202	0.933	500	500	7	1500	>4.432	500	500
10	*	*	>1600	1110	0.130	1202	0.933	500	500	7	1500	>4.432	500	500
10	*	*	>1600	1110	0.130	1202	0.933	500	500	7	1500	>4.432	500	500
2	*	*	>1600	939	0.115	1471	1.033	500	500	9	1500	>4.432	500	500
10	*	*	>1600	939	0.115	1471	1.033	500	500	9	1500	>4.432	500	500
10	*	*	>1600	939	0.115	1471	1.033	500	500	9	1500	>4.432	500	500
2	*	*	>1600	1012	0.124	1339	0.985	500	500	8	1500	>4.432	500	500
10	*	*	>1600	1012	0.124	1339	0.985	500	500	8	1500	>4.432	500	500
10	*	*	>1600	1012	0.124	1339	0.985	500	500	8	1500	>4.432	500	500

# SYSTEM SAFETY

- Propellant Feed System GN<sub>2</sub> Purges are isolated by flow check valves, enabling instantaneous on-demand flow, thus reducing:
  - Eliminating Risk of Combustion in Manifolding
  - Controlled Startup and Shutdown Characteristics.
- Computer monitoring of critical parameters for red line limits, coupled with computer controlled propellant feed system to allow rapid shutdown of test.
- Exit flare to deflagrate any excess hydrogen to prevent accumulation in ducting.
- Large circulating airflow to ensure hydrogen levels are below the flammability limits.
- Visual Monitoring of Hardware During Testing




# **RUN PROCEDURE**

- Chill Down Majority of LOX Feed System
- Load  $\text{GH}_2$  System, and LOX Tank
- Verify Computer Controlled Valve Actuation Program is correct
- Set Required Cooling Water Flowrate
- Run LOX-side Flowcheck/System Chill-down
- Initiate LOX &  $\text{GH}_2$  Purges
- Verify Ignitor Operation
- Initiate Flare
- Engage Data System, and Initiate Programmed Valve Actuation
- Once Test is completed, secure LOX system. Allow 10 minutes for cell purging, or secure facility if end of test day
- Inspect hardware and review data

# STARTING SEQUENCE

- A final system checkout is performed with the valves controlled manually. Computer control is armed just prior to actual testing
- Experimentally determined feed system fill times are corrected by sequencing the valve actuations
- Engine firing must be within operating parameters once igniter is turned off, or run is automatically terminated



# TEST PLANNING

- EACH RUN IS PERFORMED VIA A RUN DATA SHEET
- PROMOTES VISIBILITY OF TEST CONDITIONS
- ALLOWS EFFICIENT TRACKING OF TEST CONDITIONS
- PROVIDES QUICK REFERENCE FOR ALL PERSONNEL

## TEST RUN DATA SHEET RBCC CALORIMETER

RUN NO. \_\_\_\_\_ RUN DATE: \_\_\_\_\_

### RUN CONDITIONS:

LOX Venturi Pressure: \_\_\_\_\_ psia LOX Tank Pressure: \_\_\_\_\_ psia

H<sub>2</sub> Venturi Pressure: \_\_\_\_\_ psia H<sub>2</sub> Supply Pressure: \_\_\_\_\_ psia

Cooling Water Flow: \_\_\_\_\_ lb/sec Water Tank Pressure: \_\_\_\_\_ psia

N<sub>2</sub> Purge Pressure (LOX): \_\_\_\_\_ psia N<sub>2</sub> Purge Pressure (H<sub>2</sub>): \_\_\_\_\_ psia

H<sub>2</sub>/Air Ignitor Pressure  
Air \_\_\_\_\_ psig  
H<sub>2</sub> \_\_\_\_\_ psig

Exhauster required? \_\_\_\_yes \_\_\_\_no

Exhaust Torch Pressure  
Air \_\_\_\_\_ psig  
H<sub>2</sub> \_\_\_\_\_ psig

H<sub>2</sub>, LOX, Ignitor Timing (0 time is start of startup or shutdown)

Startup: LOX on \_\_\_\_\_ sec  
H<sub>2</sub> on \_\_\_\_\_ sec  
Ignitor on \_\_\_\_\_ sec  
Ignitor off \_\_\_\_\_ sec

Shutdown: LOX off \_\_\_\_\_ sec  
H<sub>2</sub> off \_\_\_\_\_ sec

Ignitor Operating Cycle: \_\_\_\_\_ ms on, \_\_\_\_\_ ms Off (repeating cycle)

Chamber Burn Duration: \_\_\_\_\_ sec

### Operating Shut Down Limits:

Water out temp. (16 places) > \_\_\_\_\_ F Water flow < \_\_\_\_\_ lb/sec  
Water out press. (16 places) < \_\_\_\_\_ psia  
Chamber Press (after ignitor off) < Pt1 < \_\_\_\_\_ psia

### RUN DESCRIPTION:

### APPROVALS:

Engineering

J. Mays

Operations

B.R. Ellis

Project

R. Wieveg

H:\MSWORD\Testshd.doc

R Wieveg

**ATTACHMENT II**

**CALORIMETER INJECTOR PLATE - STRESS ANALYSIS**

KAISER MARQUARDT  
INTEROFFICE MEMORANDUM

June 16, 1997  
file: inj3.1

TO: R. Wieveg  
FROM: A. Runyon  
SUBJECT: RBCC - CALORIMETER INJECTOR PLATE - STRESS ANALYSIS  
RECOMMENDED PROOF PRESSURE & STRESS IN LIGAMENT BETWEEN  
INLET AND OUTLET PLENUMS

COPIES: T. Chen, D. Lucci, S. Bartlett, R. Humphrey

REFERENCES :

1. IOM to R. Wieveg from A. Runyon, RBCC- CALORIMETER IN-  
JECTOR PLATE - STRESS ANALYSIS., Jan. 14, 1997.
- 

INTRODUCTION :

The stress analysis of Reference 1 was reviewed and modified in the light of certain problems with the copper Injector X42801A of the Calorimeter. The following tasks were addressed. The Injector is shown in Figure 1.

- TASK 1. Considering that the Injector yielded excessively at a proof pressure of 1,000 psi, what should be the revised Proof pressure ?
- TASK 2. Check the ligament between the inlet and outlet plenums. What magnitude stress causes failure across the section?

DISCUSSION AND RESULTS :

TASK 1 :

The stress model of the Injector from Ref. 1 was revised to conservatively account for the .082 inch diameter holes which were previously ignored. The reduced section properties are dated "6-13-97" in Figure 2: the dimensions are shown in Figure 3. Plots of the old and revised bending moments of inertia are shown in Figure 4. Figure 5 shows the stress vs. strain curve of OFHC copper at 70 degrees F.

The results for two pressures are shown below:

FIGURE 5	PRESSURE (PSI)	STRESS (PSI)	DEFLECTION (INCH)	STRAIN (IN/IN)
POINT A	1,000	9,875	.0015	PLASTIC RANGE
POINT B	700	6,913	.0011	.00038

It is seen from the stress versus strain curve that 1000 psi pressure will cause plastic straining up to .010 in/inch. This is excessive and should be reduced to 700 psi which will keep the stress in the elastic range of the copper material.

The recommended proof pressure is 700 psig.

#### TASK 2 :

The finite element model shown in Figure 6 was used to assess the probability of a failure across the ligament caused by pressurization alone. The results for maximum stress in the ligament are as follows for three cases at 1000 psi pressure.

CASE	PRESSURIZED REGIONS	MAX STRESS (PSI)	ULTIMATE STRENGTH AT 70 DEGREES F (PSI)
A	PLENUMS 1, 2 AND HOLES	7,880	15,000
B	PLENUM 1 ONLY	6,845	15,000
C	PLENUM 2 ONLY	5,420	15,000

Reviewing the above numbers shows no reason to believe that excessive stress is the cause of failure.

The pressure to cause failure is estimated as

$$(15,000 / 7,880) * (1000) = 1900 \text{ psig}$$





FIGURE 1

1 x 2.85

oper  
p = 500 PSI operating  
70-120°F

1/15/49

AR 1-14-97

FIGURE 2

B4

CHECKED BY 6-13-97

CLASSIFICATION

DATE

PAGE

RBCC


5 OF 5

INJECTOR PLATE model. 2COPPERLOADING

$$W = 1,000 (1.0) \\ = 1,000 \text{ LB/IN}$$

$$E = 17.0 \text{ E6 PSI}$$


$$\nu = .3$$

SECTION ①

$$A = 1.25 (0.812) \\ = 1.015 \text{ IN}^2$$

$$I_y = \frac{1.25 (0.812)^3}{12} = .0558 \text{ IN}^4$$

$$I_z = \frac{0.812 (1.25)^3}{12} = .1322 \text{ IN}^4$$

LOADING ON NODES

NODE 3	$F_y = -1000 (.15) =$	$.150.0$
4	$= - (.154.05) =$	$200.0$
5	$= (.054 .1665) =$	$216.5$
6	$= (.333) =$	$333.0$
7	$= (.333) =$	$333.0$
8	$= (-.1665) =$	$166.5$

1900.0 Per 1/2 model 27800 TOTAL

ANALYSIS STIFF INPUT

PROP	A	A	$I_{yz}$	$I_{yy}$	$T_{Kz}$	$-T_{Ky}$	$I_{xx}$	$S_{xz}, S_{xy}$	$I_{x/c}$
	1	2	3	4	5	8	9, 10		
1	1.015	.1322	.0558	.812	1.250	.188	1.2162	.1374	
2	0.878	.1120	.0447	.843	1.326	.157	↓ ↓	.1061	
3	0.957	.1149	.0783	1.181	1.315	.193	↓ ↓	.1326	
3	0.834	.1135	.0661	1.181	1.315	.131	↓ ↓	.1119	
4	0.896	.1135	.0554	1.012	1.321	.126	↓ ↓	.1095	
1, 2 Same as Before									

FORM TMC 105 REV. 2-70



FIGURE 3

FIGURE 4

PROPERTY 3 WITH HOLES






FIGURE 4  
INJECTOR PLATE  
BENDING MOMENT OF INERTIA



67

FIGURE 5





Figure 26 Typical Stress-Strain Curves for OFHC Copper Annealed Condition



INJECTOR CROSS-SECTION

FIGURE 6

**ATTACHMENT III**

**CALORIMETER FAILURE ANALYSIS BY RON COOK**

**RBCC  
CALORIMETER  
FAILURE ANALYSIS**

**HOT FIRE TEST #R1038**

**Ron Cook**

**June 11, 1997**

**KAISER MARQUARDT**

**COMPETITION SENSITIVE**

## FAILURE MODE

- Cause of Failure
  - LOX in Injector and Facility H<sub>2</sub> Feed System
- Failure Triggered by: (Sequence of Events)
  - Delayed Ignition (by ~ 300 msec)
  - Resulted in Combustor Hard Start
  - High Temperature Combustion Gases Driven into LOX and GH<sub>2</sub> Feed Systems
  - Ignition of LOX/H<sub>2</sub> Mixture in H<sub>2</sub> Feed System
  - Burn-Out of Injector H<sub>2</sub> Feed Tube
  - Major LOX Fire Vaporizes Injector Material Leaving No Traceability of Which Came First

**KAISER MARQUARDT**

*COMPETITION SENSITIVE*

# SCENARIO

## Ways of Transferring LOX into H<sub>2</sub> System

- Injector Inter-Propellant Leak
- Malfunction of LOX GN<sub>2</sub> Purge Check Valve
  - Failed-OPEN During Start Transient and Mainstage
- Malfunction of GH<sub>2</sub> GN<sub>2</sub> Purge Check Valve
  - Failed-CLOSED During Pre-Test LOX Blowdown (Bleed Through Injector)

**KAISER MARQUARDT**

COMPETITION SENSITIVE



## **ANALYSIS APPROACH**

- Review Facility Flow & Instrumentation Schematic
- Review Hot Fire Test Data
  - Identify Sequence of Events
  - Discuss Pressure & Temperature Levels and Activities
- Review LOX and GH2 Blowdown Data (run # R1003, -4, -5)
  - Discuss Pressure Profiles and Valve Sequencing
- Compare LOX Blowdown Data and Hot Fire Data
  - Point Out Significant Differences
  - Identify Scenario for These Differences
- Define Which Ways are Amenable to Transfer LOX into H2 System
  - Based on Hot Fire Data
- Conclusion
- Recommendations

***KAISER MARQUARDT***

*COMPETITION SENSITIVE*

## BLOWDOWN DATA & ANOMALIES

- Hydrogen
  - Crisp & Responsive (as would be expected), P-venturi = 1,700 psi
  - High Run Valve  $\Delta P$  - H2 Venturi Barely Choked
    - H2 Choked Across Run Valve but Venturi Controls H2 Flowrate)
- Oxygen
  - Run R1004
    - Crisp & Responsive - Good LOX Quality
    - Purge GN2 Pressure Locked-up at 370 psig
    - Very High Injector  $\Delta P$  = 900 psi
  - Run R1003
    - Crisp & Responsive - Fair LOX Quality (Gas Bubble in System), P-venturi = 1,500 psi
    - Purge GN2 Pressure Locked-up at 370 psig
    - Very High Injector  $\Delta P$  = 800 psi

**KAISER MARQUARDT**

COMPETITION SENSITIVE

# LOX BLOWDOWN DATA ANALYSIS

- PROBLEM
  - || AP Injector ~ 5X Higher Than Expected for LOX Flow Rate Based on Venturi Flowrate for Hot Fire Venturi Throat Area
- CONCLUSION
  - LOX Venturi Throat Area > 2X A\* for Hot Fire Test Based on Injector AP and Crisp vs. Sluggish Start on Hot Fire Test
    - Good vs. Poor Quality LOX
  - LOX Mass Flow for LOX Blowdown is 2.5 to 3 X of LOX Flow Rate during Hot Fire

**KAISER MARQUARDT**

COMPEITION SENSITIVE

# COMPARISON OF LOX GN2 PURGES (LOX Blowdown vs. Hot Fire)

- HOT FIRE DATA
  - P venturi = 370 psig
  - P injector = 80 psig
- LOW BLOWDOWN
  - P venturi = 370 psig
  - P injector = 370 psig
- CONCLUSION
  - GN2 Purge Plumbed Downstream of Venturi for LOX Blowdown
  - GN2 Purge Plumbed Upstream of Venturi for Hot Fire Test

**KAISER MARQUARDT**

**COMPETITION SENSITIVE**

# **FAILURE MODE SCENARIO**


## **Analysis of Transferring LOX into GH2 System**


- INJECTOR INTERPROPELLANT LEAK
  - LOX Can Not be Transferred to H2 System Since LOX Injection Pressure Never Exceeds H2 Injection Pressure
- MALFUNCTION OF LOX GN2 PURGE CHECK VALVE
  - Enormous  $\Delta P$  available to transfer LOX into H2 System
- MALFUNCTION OF GH2 GN2 PURGE CHECK VALVE
  - Pc with Purges ON (pre-test) Reflects both LOX and GH2 Purges Working Normal
- CONCLUSION
  - LOX was Transferred to the GH2 System by Malfunction of LOX GN2 Check Valve.

**KAISER MARQUARDT**


COMPETITION SENSITIVE

# CALORIMETER TEST SET UP PIPING AND INSTRUMENTATION DIAGRAM





# RBCC CALORIMETER CHAMBER LOX SYSTEM (INSIDE)




*Handwritten signature/initials*

FOAM INSULATED 1" x .083 SS TUBING

## HYDROGEN SYSTEM (FUEL)


1/2" x .049 SS TUBE -




16/10/1961




# HOTFIRE RESPONSE - R1038




**HOTFIRE RESPONSE - R1038**



# LOX DATA - R1038




GH2 DATA - R1038







R1036 - LOX COLD FLOW




LOX SYSTEM RESPONSE



LOX COLD FLOW RESPONSE - R1003







GH2 RESPONSE - RUN 1005

PI2  
PI1  
VH2  
HP  
HP

**ATTACHMENT IV**

**CALORIMETER TEST PLUMBING AND OPERATIONS MODIFICATIONS**

**KAISER  
MARQUARDT**

## Interoffice Memo

**To:** Distribution

**Date:** 6/19/97

**From:** R. Wieveg *RW*

**Ref:** 970619.doc

**Subject:** Calorimeter Test Plumbing and Operation Modifications

**CC:**

---

As a result of the failure investigation following the failure of the calorimeter injector in cell 8, The attached modifications to the plumbing/control system and operation procedures are recommended.

A new, gas/gas start up propellant flow system has been added. This system will allow less violent starts and permit development of a satisfactory start sequence without destroying the test hardware. Gas hydrogen and gas oxygen are admitted to the chamber during the 1<sup>st</sup> phase of the ignition cycle. This gas mixture is easily ignited by the hydrogen air ignitor prior to introduction of the liquid oxygen and full gas hydrogen flow. Combustion chamber pressure during the gas/gas ignition phase will be controlled to about 75 to 150 psia. After verification by combustion chamber pressure of ignition, the liquid oxygen and high pressure hydrogen flow will be initiated, with constant monitoring of chamber pressure to insure continuous combustion. A rapid drop in chamber pressure (resulting from flame out) will initiate automatic shut down of propellant flows and initiate nitrogen purges in both the hydrogen and oxygen systems.

The nitrogen purge for the hydrogen system will be moved to enter the hydrogen flow line just upstream of the venturi and the venturi will be moved to a location downstream of the hydrogen flow shut off valve. Double check valves will be installed in both the hydrogen and oxygen purge lines at the point where they enter their respective propellant flow lines. Existing check valves in the purge and propellant lines will be removed and checked for leak free operation before being re-installed.

Additional instrumentation to provide propellant conditions at the entrance to the injector head will be installed. Automatic control of the gas/gas start up flow control valves and the hydrogen and oxygen purge shut off valves will be added to permit accurate timing and sequencing of these important functions.

**Distribution:**

S. Bartlett, T. Chen, ~~XXXXXXXXXX~~, W. Kelly, A. Lucci, J. Mays, D. Ruttle

**RBCC PLUMBING MODIFICATIONS**  
**6/19/97**

1. Install H <sub>2</sub> venturi downstream of cross (like O <sub>2</sub> ), Move P and T instrumentation to match.	16 hrs
2. Move all plumbing from shutoff valves to engine so line lengths are <b><u>MINIMIZED.</u></b>	16hrs
3. Install P and T readouts at LOX and GH2 inlet connections on the injector.	16hrs
4. Move P chamber xducer lines from injector to chamber ports.	6hrs
5. Move ignitor from injector port to chamber port.	4hrs
6. Add start up GOX and Gh2 plumbing and controls.	20hrs
7. Add computer control of start up GOX and GH2 valves and LOX and GH2 purge valves.	10hrs
8. System Leak, Function, and flow checks.	24hrs
9. Remove, Test, and replace 4 check valves.	8hrs
10. Scrounge and clean up 4 check valves, 2 shutoff valves and 3 Regulators	24hrs
Contingency 10%	14hrs
<b><u>TOTAL</u></b> .....	<b>158hrs</b>

**RBCC CALORIMETER TEST**  
**NEW OPERATING PROCEDURES**

**6/19/97**

**LOX COLD FLOW:**

1. Turn on cooling water (4.5 #/sec min.)
2. Cool down/fill LOX tank/Line.
3. Set N<sub>2</sub> Purge Static (non flowing) pressure to 500 psia
4. Turn on H<sub>2</sub> and LOX purge valves
5. Pressurize LOX tank to \_\_\_\_\_ psia.
6. Manually open LOX flow valve  
    When LOX temp at injector is <-260°F, set flow pressure at venturi to run condition.
7. Shut off LOX flow valve.
8. Shut off LOX purge and GH<sub>2</sub> purge valves
9. Wait for 5 minutes
10. open LOX purge and GH<sub>2</sub> purge valves
11. Run Automatic(computer controlled) LOX only flow with data recording for 10 seconds.
12. Repeat from step 6. For all 4 LOX flow ponts.
13. Vent and secure LOX system
14. Turn off cooling water
15. Turn off LOX and GH<sub>2</sub> purge valves.

**RBCC CALORIMETER TEST**  
**NEW OPERATING PROCEDURES**  
**6/19/97**

**GH<sub>2</sub> COLD FLOW:**

1. Turn on cooling water ( 4.5 #/sec min.)
2. Turn on exhaust duct water sprays.
3. Turn on exhaust flare
4. Set GN<sub>2</sub> purge pressure to 500 psia (static)
5. Turn on GH<sub>2</sub> and LOX purge valves
6. Open GH<sub>2</sub> run valve and adjust GH<sub>2</sub> regulator to five \_\_\_\_\_ psia Pto at venturi
7. Close GH<sub>2</sub> run valve
8. Run Automatic (computer controlled) GH<sub>2</sub> only flow with data recording for 10 seconds
9. Repeat from step 6 for all 4 GH<sub>2</sub> flow conditions (note GH<sub>2</sub> regulator loading pressure at each Pto (venturi) setting
10. Shut off GH<sub>2</sub> and LOX purge valves
11. Shut off flare
12. Shut off cooling water to test item
13. Shut off exhaust duct cooling water
14. Secure GH<sub>2</sub> system

**RBCC CALORIMETER TEST**  
**NEW OPERATING PROCEDURES**

**6/19/97**

**HOT FIRE RUN:**

1. Cool down LOX system to run valve
2. Verify run sequence properly loaded into computer
3. Set GH<sub>2</sub> regulator loading pressure per run sheet
4. Set GN<sub>2</sub> purge pressure to 500 psia (static)
5. Turn on LOX and GH<sub>2</sub> purge valves
6. Turn on test item cooling water
7. Set startup LOX pressure to 300 psia
8. Set startup GH<sub>2</sub> pressure to 150 psia
9. Set ignitor air and hydrogen pressure to 265 psia
10. Start exhausters, open cell air bleed
11. Turn on exhaust cooling water
12. Pressurize LOX tank per run sheet
13. Manually cold flow LOX, set venturi inlet pressure per run sheet after temp at injector inlet is < -260°F
14. Close LOX run valve
15. Light exhaust flare
16. Fire engine (automatic controlled by computer, see auto fire timing sheet)
17. If this is the last run of the series, go to step 21
18. Reset GH<sub>2</sub> regulator for next run condition
19. Turn off exhaust flare
20. Repeat from step 13
21. Turn off LOX and GH<sub>2</sub> purge valves
22. Vent and secure LOX system
23. Turn off cooling water
24. Turn off exhaust flare
25. Secure exhausters
26. Secure GH<sub>2</sub> system

**RBCC CALORIMETER TEST**  
**NEW OPERATING PROCEDURES**

**6/19/97**

**HOT FIRE TIMING:**

<b><u>Time - Seconds</u></b>	<b><u>Function</u></b>
0.000	close LOX & GH <sub>2</sub> purge valves
0.150	Turn on ignitor
0.200	Turn on start up GOX valve
0.250	Turn on start up GH <sub>2</sub> valve
1.000	Turn off ignitor
	Verify ignition- (Pch > 85 psia)
	If no ignition ---
	Shut off GH <sub>2</sub> and GOX start up valves
	Secure System
	If ignition proved ---
1.150	Open LOX run valve
1.350	Open GH <sub>2</sub> run valve
1.600	Verify main ignition (Pch > 400 psia)
	if no ignition ---
	Open LOX and GH <sub>2</sub> purge valves
	Close LOX run valve
	Close GOX start up valve
	Close GH <sub>2</sub> start up valve
	Close GH <sub>2</sub> run valve
	Secure system
	If ignition proved ---
	Open LOX and GH <sub>2</sub> purge valves
	Continue run to preselected time limit
Run time limit	Close LOX run valve
	Close GOX start up valve
	Close GH <sub>2</sub> start up valve
	Close Gh <sub>2</sub> run valve
Run time limit + 30	Close LOX and GH <sub>2</sub> purge valves after 30 sec.
sec	Secure system



**RBCC CALORIMETER TEST**  
**NEW OPERATING PROCEDURES**  
**6/19/97**


**LOX COLD FLOW TIMING:**

<b><u>Time - Seconds</u></b>	<b><u>Function</u></b>
0.000	close LOX & GH <sub>2</sub> purge valves
0.200	Turn on start up GOX valve
1.150	Open LOX run valve
1.600	Open LOX and GH <sub>2</sub> purge valves
	Continue run to preselected time limit
Run time limit	Close LOX run valve
	Close GOX start up valve
Run time limit + 30 sec	Close LOX and GH <sub>2</sub> purge valves after 30 sec. Secure system


**GH<sub>2</sub> COLD FLOW TIMING:**

<b><u>Time - Seconds</u></b>	<b><u>Function</u></b>
0.000	close LOX & GH <sub>2</sub> purge valves
0.250	Turn on start up GH <sub>2</sub> valve
1.350	Open GH <sub>2</sub> run valve
1.600	Open LOX and GH <sub>2</sub> purge valves
	Continue run to preselected time limit
Run time limit	Close GH <sub>2</sub> start up valve
	Close Gh <sub>2</sub> run valve
Run time limit + 30 sec	Close LOX and GH <sub>2</sub> purge valves after 30 sec. Secure system

# CALORIMETER LOX SYSTEM



# CALORIMETER H2 SYSTEM



START UP  $O_2$  &  $H_2$  Pressure Settings

OXYGEN INJECTOR ORIFICE AREA - 20 ga .0364 Holes

HYDROGEN INJECTOR ORIFICE AREA - 10 ga .0654 Holes

NOMINAL START UP CONDITIONS:  $W_{O_2} = .2 \text{ LB/sec}$

$$K_{O_2} = 2.5$$

$$W_{H_2} = .05 \text{ or less } (C/F = .4)$$

$$K_{H_2} = 4.0$$

$CO_2$  Flow (Choked)

$$A_{H_2} = .056 \text{ in}^2$$

$$W = \frac{.545 \times P \times A_{O_2} \times C_0}{\sqrt{530}}$$

$$A_{O_2} = .001018 \text{ in}^2 \times 20 = .02036$$

UNCHOKED

$$\Delta P = \left( \frac{F}{Q} + K \right) \left( \frac{W}{A} \right)^2 \frac{RT}{ZgP}$$

$$R = 48.25$$

$$T = 530^\circ R$$

~~SIZE FOR  $\Delta P = 50 \text{ PSI}$~~

ASSUME  $P = 150 \text{ PSIA}$

$$\Delta P = 2.5 \left( \frac{.2}{.02036} \right)^2 \frac{48.25 \times 530}{64.4 \times 150} = 638 \text{ PSI} - \text{CAN'T DO IT.}$$

$$\text{UNIT OK} - \frac{\text{LB}^2}{\text{SEC}^2} \frac{\text{FT}^2}{\text{LB}} \frac{\text{RT}}{\text{RT}} \text{ OK}$$

TRY USING  $\Delta P = 100 \text{ PSI}$ ,  $P = 200 \text{ PSI}$

FIND FLOW

$$\left( \frac{W}{A} \right)^2 = \frac{\Delta P \times ZgP}{RTK}$$

$$W = \sqrt{\frac{2 \Delta P g P A^2}{RTK}}$$

$$\text{UNCHOKED } W = \sqrt{\frac{2 \times 100 \times 64.4 \times 200 \times .02036^2}{48.25 \times 530 \times 2.5}} = .129 \text{ LB/sec}$$

$$\text{CHOKED. } W = \frac{.545 \times 200 \times .02036 \times .75}{\sqrt{530}} = .0722 \text{ LB/sec.}$$

USE 200 PSI FOR  $GOX$  SUPPLY PRESS, SIZE

$H_2$  PRESS TO GIVE .025 TO .035 LB/sec @ 100 PSI  $P_d$ .

$$\Delta P_{H_2} = 4 \times \left( \frac{.035}{.056} \right)^2 \frac{772 \times 530}{64.4 \times 130} = 76 \text{ psi}$$

Change P. to 150,

$$\Delta P_{H_2} = 66.$$

P = 166 USE 150 PSI ON H<sub>2</sub>

$$\text{THEN } W_{H_2} = \sqrt{\frac{2 \times 50 \times 64.4 \times 150 \times .056^2}{772 \times 530 \times 4}} = \frac{1043}{\cancel{1043}} \text{ LB/SEC}$$

O<sub>2</sub> checked @ 200 PSIA

$$W_{O_2} = .0722 \text{ LB/SEC}$$

$$O/F = \frac{.0722}{.043} = 1.67 - \text{KIND OF HIGH K. BUT MAY WORK.}$$

LET'S USE 300 ON O<sub>2</sub> PRESS,  
SHOULD WORK BETTER

CONCLUSION -

$$\left. \begin{array}{l} P_{O_2} = 300 \text{ PSIA} \\ P_{H_2} = 150 \text{ PSIA} \end{array} \right\} \text{IGNITION CONDITION}$$

$$W_{T} = .043 + .1083 = .1151 \text{ LB/SEC}$$

$$P_{st} \approx \sqrt{\frac{1}{.115}} \times 500 = 57.5 \text{ PSI}$$

Clamton  
Press @ Star